

HPDE 1 & GR Program

10/3-10/4

Drivers Information Packet



Welcome to NASA Utah! we are happy to share this driving experience with you. Exploring the limits in a safe environment is our goal and a great way for you to learn more about the physics of racing. Be sure to take advantage of the NASA instructors and group leaders for their wealth of knowledge and experience. They can help you reach your driving goals. We hope you enjoy the West Track with NASA Utah and look forward to helping you progress!

Please take a few minutes to read this packet and check the website for daily schedule and paddock map posted by Wednesday.

Daily Schedule: www.nasautah.com - You are responsible for making sure you are where you need to be when you need to be there.

- Check in at the NASA Office – Team Garage #109 – first thing in the morning.
- Be to Grid 10 minutes before your schedule says your run group is scheduled. A sign board adjacent to grid will communicate which group is on track, and which should be in grid!
- Grid is first come first serve.
- On Sunday 10/4 Grid moves at the halfway point through the day. Make sure you pay attention to where and when your grid location changes.
- We are not responsible if you miss your session. Keep an eye on the grid boards, and the schedule!
- **Bring tech form to drivers meeting!**
- Your Driver's Meetings are **MANDATORY**, please check schedule!
- Paddock Parking –
 - Paddock Map will be posted to www.nasautah.com and sent via email by Wednesday before the event
 - For this event there is a reserved HPDE1 parking area near your Classroom. Please find it on the Paddock Map, or ask at the NASA Office
 - PLEASE only park your car you're using on track in the HPDE1 reserved area
 - If you tow your car out, or bring additional vehicles, please review and Follow the [WD paddock parking rules](#)

Fundamentals are the same for all our drivers

- **Be Safe** – car comes home in the same condition it came to the track in – minus some tire and brake pad life.
- **Have Fun** – we come out to have fun and challenge ourselves and our cars.
- **Go Fast(er)** – we want to improve our car control skills.

Communications

For effective communication between drivers and NASA Utah staff, the following items are required to participate.

1. Complete review of this entire document. Due to the complexities of operating a track event, standard operating procedures/rules will be outlined below. Meetings will focus on working out kinks in operations, coaching group performance, etc.
- 2. HPDE 1 will be meeting in Classroom 4, west end of west day garages.**
3. Your HPDE leaders can be reached during non-meeting times via text or call, they will share the number in your morning meeting. They will also tell you where in the paddock they can be found.

Please note that both group leaders also participate or support one or more other groups and may not be available during those sessions.

General Rules - All Groups

- Passing (see map below)
 - **Read the HPDE Course conduct section in the [CCR – Section 6.0](#)**
 - Point by is required. This means the lead car uses a clear arm out the left side window to indicate it is safe to pass. Lead car stays on line, while overtaking car executes the pass by moving off line and around. Use only the marked straights outlined below in the passing map. Stay in touch with leaders after each session, they may add additional passing zones if needed.
 - If a train forms (multiple cars waiting patiently to make passes safely) it can be difficult to break them up. Please feel free to use the pit to break up the train. This means simply exit the course at West Turn 10, and drive at speed limit thru pit right back up to track entry. Look to the course worker at the track entry for a signal to wait or enter track. They will try to put you in a space of clear track, this can take 20-30 seconds.
 - Dive-bomb passes will not be tolerated.
 - It's a huge track, and car counts in HPDE 1 are intentionally low. Find space and enjoy!
 - **No cars side-by-side in corners**
 - **Single car passing, no 3 wide passes!**
 - If you are having a mechanical issue and are exiting track, maintain one side of the track, provide the 'exiting course' hand signal (fist in the air, out of window), maintain slower pace and be predictable.
 - If you cannot complete the pass during the acceleration zone, please back out and plan for the next passing zone. Be courteous, low car count means lots of track space for drivers.
- **Pit and Paddock Rules**
 - **Anyone in hot pits needs a wristband. No minors or pets on hot pits.**
 - Pit Lane Speed Limit: **25MPH**
 - Paddock Speed Limit: **5MPH**
- **Last Lap of Session**

- Passing is still allowed in passing zones, but keep in mind that you should begin a cool-down lap at the half-way point through your final lap and some drivers are not expecting a pass on cool down laps, use caution!
- Checkered flag will be thrown at:
 - For Outer Track – All day Saturday
 - Start/Finish
 - Blackrock Hairpin (Turn 5)
 - Tooele Turn (Turn 11)
 - For East Track – Sunday am.
 - Start/Finish
 - Tooele Turn (Turn 11)
 - For West Track – Sunday pm.
 - Start/Finish
 - Blackrock Hairpin (Turn 5)
- **Exiting Course**
 - Left hand out window at a right angle – either closed fist or fingers pointing to the sky
 - Pit Lane Speed Limit: **25MPH**
 - For further info, read the CCR page 24 section 8.1
- **Flags –**
 - See Flags at end of this document for standard flag explanations.
 - Black flag station will be manned, but communication will be limited as described above. Get stopped, take a breath, and wait for instructions. We will communicate and get you back on track/
- **Grid**
 - **Please Check Paddock Map for Location**
 - Please get to grid 10 minutes early
 - Helmets on, seatbelts buckled, front windows down
 - Please remain in your vehicle and keep staff/support to a minimum.
 - Enter thru yellow flag cones at north end of grid
- **Instruction / Instructors / Passengers**
 - **Only instructors are allowed to take passengers.**
 - You will meet your instructors on the grid before your session begins. So get to grid a few minutes early to meet and debrief with your instructor on your goals for the session!

Other resources:


Link to CCR - [Club Codes and regulations](#)

NASA Utah website (for schedule, tech forms, etc.) - www.nasautah.com


Link to update your NASA member info (for ensuring your cell phone number is correct so we can send you SMS alerts) - [DriveNasa sign in page](#)

Passing Zones


Outer Track – Saturday



East Track – Sunday am.



West Track – Sunday pm.



Flags (source: NASA National CCR)

HIGH PERFORMANCE DRIVING AND TIME TRIALS

7.0 HPDE, SCHOOL, AND OPEN TRACK FLAGS

Flags are the MOST IMPORTANT form of communication the Officials have with the drivers while they are on the track. Therefore, it is imperative that drivers know what each flag means.

Note: Flags listed in this section are simplified from the Competition Flags, for the purposes of HPDE Program. Competition License Candidates are held responsible for the information contained in the "FLAGS, SIGNALS, AND COMMUNICATION" section #19.0 of the CCR.

7.1 Green Flag



Session is open.

7.2 Yellow Flag - Motionless



Slow down. Danger ahead. **ABSOLUTELY NO PASSING** is permitted, until completely past the incident, or until past next manned flag station that is not displaying any Yellow Flag(s), whichever comes first. There may be one (1) yellow flag covering more than one incident. There may be several yellow flags before reaching the emergency area. The requirements are still the same, "SLOW DOWN, NO PASSING." [Ref:(25.4.1)]

7.3 Yellow Flag - Waving



Great danger, slow down. Be prepared to stop. **ABSOLUTELY NO PASSING** is permitted, until completely past the incident, or until past the next manned flag station that is not displaying any Yellow Flag(s), whichever comes first. Note: There may be one (1) yellow flag covering more than one incident. [Ref:(25.4.1)]

7.4 Double Yellow Flags



Full course yellow condition exists. Be prepared to encounter a Pace Car and/or emergency vehicles. Drivers should not significantly slow down. Be prepared to encounter a slow moving pack and other local flag conditions. Always obey the local flag conditions (e.g. waving yellow). **ABSOLUTELY NO PASSING** is permitted, until the Pace Car (if on track) has pulled off AND the driver has passed the next manned flag station that is not displaying any Yellow Flag(s). [Ref:(25.4.1)]

7.5 Black Flag - Open



Track Officials want to talk to you. Complete current lap and pull into the pits for consultation.

7.6 Black Flag - Furred



Warning. You are driving in an unsafe manner or you did something wrong. If you continue to do so, an open black flag will be shown to you.

7.7 Black Flag All - Waving



All manned flag stations will display waving black flags during this condition. Some flag stations might display a sign with the word "ALL." All cars proceed slowly to the hot pits. No passing.

(continues below)

HIGH PERFORMANCE DRIVING AND TIME TRIALS

7.8 Checkered Flag



Session is over. Complete current lap cautiously and exit via pit lane or otherwise designated end-of-session track exit point. Passing rules remain the same during the checkered flag lap as during the session.

7.9 Red Flag



Emergency. Come to an immediate and controlled stop on the side of the track in a safe location.

7.10 Blue Flag



(with diagonal yellow stripe)

Another vehicle is following very closely and may attempt a pass. The driver receiving the Blue Flag should consider giving a passing signal.

7.11 Debris Flag



(yellow and red stripes)

Caution. To be displayed motionless. Oil or debris may be present on the track surface or a slippery condition may be present. This flag will be taken down after several laps, but that does not mean that the condition has resolved, just that the driver should now be taking it into account

7.12 White Flag



Emergency vehicle or slow moving vehicle is on course.

7.13 Emergency Vehicle Flag



(white flag with a red cross)

There is an emergency vehicle on course. Pass with extreme caution.

7.14 Mechanical Black Flag



(with orange ball in center)

(a.k.a. *meatball flag*) There appears to be something mechanically wrong with your car. Proceed to the pits at reduced speed.

7.15 Pace Car (with lights on)



Follow the Pace Car at about the same speed. Do not pass the Pace Car unless instructed to do so by the Pace Car personnel. Passing is only allowed after the Pace Car has pulled off AND the driver has passed the next manned flag station that is not displaying a yellow flag.